

Figure 1






Figure 2A



MULTICHIP CERAMIC PACKAGE 28






Figure 2B




DEFECTIVE PART WITH INTERMITTENT SHORT (W1008)




Ohms, Vcc to Ground

Figure 3A




PART W1008 AFTER REMOVAL OF SHORT



Ohms, Vcc to Ground

Figure 3B



DEFECTIVE EPOXY CONTACT ON PART (W1020)






Figure 4



PART W1020 AFTER REPAIR OF DEFECTIVE EPOXY CONTACT



Ohms, Vcc to Ground

Figure 5





FIG. 6A




FIG. 6B

